



Product Data Sheet BrickImaging BASE Compound

PRODUCT DESCRIPTION:

BASE is a high-quality exterior 100% acrylic latex that dries to a durable flat finish. The 100% acrylic technology provides excellent fade resistance, which allows colors to remain beautiful for years.

USE:

Formulated for use on masonry surfaces.

PHYSICAL PROPERTIES:

SURFACE PREPARATION:

<p>Resin Type Clean-up Solvent Finish Solids by Weight Solids by Volume</p> <p>Recommended Dry Film Thickness per Coat</p> <p>Wet Film to achieve DFT</p> <p>Theoretical Coverage @ 1 mil</p> <p>Practical Coverage at Recommended DFT</p> <p>Dry Times: @ 70° F (21° C) hours</p> <p>VOC's Range from depending on color</p>	<p>100% Acrylic Latex Water 0 – 5 @ 85° F 50% 34%</p> <p>1.5-2 mils</p> <p>4.5-6 mils</p> <p>545 Sq Ft/gallon</p> <p>276-363 Sq Ft/gallon</p> <p>Touch ½ hour to 2 hours</p> <p>99 grams/liter</p>	<p>Note: All surfaces must be cured, clean, sound, dry, and free of all dust, dirt, efflorescence, wax, oil, grease, chalk and any other contaminants that would interfere with new coating adhesion.</p> <p>Brick/CMU/Mortar/Concrete: New masonry surfaces should cure for a period of 30 days at 72° F (22° C) prior to coating application. Level all surface projections and mortar spatters by stoning. Rake mortar joints clean and remove all soluble salts.</p> <p>Previously Painted Surfaces:</p> <ul style="list-style-type: none"> ▪ Paint must be removed from all masonry surfaces prior to BrickImaging staining. ▪ Chemical peels should be executed cautiously so as not to damage the texture or face of the masonry. ▪ Consult with a professional for the best paint removal application for your project. <p>Mildew: Remove by using a solution of one (1) part household bleach and three (3) parts water. Apply to mildewed area and scrub. Allow solution to remain on the surface for 3 to 5 minutes then rinse completely and allow to dry prior to staining application.</p>
---	--	---

APPLICATION:

ENVIRONMENTAL VARIABLES:

<ul style="list-style-type: none"> • Stir material prior to application. Intermix tinted containers to ensure color uniformity. • Apply as directed by BrickImaging Inc. by brushing, rolling, spraying, ragging, or other. • Contact BrickImaging with any questions regarding touch-up for your project. 	<p>Protect product from freezing prior to and during application. Minimum surface and air temperature required for application is 40° F (10° C) and at least 5° F (3° C) above the dew point. Curing is affected by temperature, humidity, and air movement. The minimums must be maintained for at least eight (8) hours for proper curing. Application at higher temperatures, wind conditions, and/or low humidity may require special application procedures to achieve proper curing.</p>
---	--

CLEAN-UP:

CAUTIONS:

<p>Clean up spills immediately with soap and warm water. Use soap and warm water to clean hands and tools immediately after use.</p>	<ul style="list-style-type: none"> • Do not apply below 40° F • Protect from freezing • Do not take internally • Use with adequate ventilation • KEEP OUT OF REACH OF CHILDREN
--	---